OUT59051

FM NPIC WASH DC TO AIG NINE SEVEN SIX RUEKDA/DIA PRODCEN RUEKDA/NIC CONFIDENTIAL CITE NPIC 7714.

REF A:

REF B:

PROCESS.

INITIAL SCAN BY NPIC OF MISSION

REVEALS BRIDGE RECONSTRUCTION ON NORTH VIETNAM ROUTE

15 AT 1757N 10548E.

- THE XOM CA TRANG HIGHWAY BRIDGE OVER THE RAO CAI (RIVER) AT UTM WE864855 IS OBSERVED TO HAVE FOUR CONSTRUCTION PLATFORM CABLES STRUNG BETWEEN TWO PIERS AS PROBABLE INITIAL RECONSTRUCTION EFFORTS FOR REPLACEMENT OF THE MISSING (DESTROYED) CONSTRUCTION MATERIAL IS ALSO OBSERVED ADJACENT TO SPAN. BRIDGE APPROACHES. IDENTICAL CONDITIONS EXIST ON THE XOM CA TRANG HIGHWAY BRIDGE OVER THE NAM QUAT (RIVER) AT UTM WE861859. WHERE ONLY THE ABUTMENTS OF THE ORIGINAL BRIDGE REMAIN. RECONDITIONING OF ALL APPROACHES IS EITHER FINISHED OR IS IN
- 2. PREVIOUS PHOTOGRAPHIC COVERAGE REVEALS THE FOLLOWING CHRONOLOGICAL ORDER OF RECONSTRUCTION:

Α.	. PHO:	rogr <i>i</i>	APH'	Y					REVE	EALED	CABLE
ANCHOR	HOLES	DUG	IN	вотн	APPROACHES	OF	THE	RAO	CAI	BRIDG	ΞE.

В.	PHOTOGRAPHY	REVEALED	THE	CABLE

8 71	JF 1200					
DISTRIBUTION 2						
Cy No.	Office	Action				
	File					
2	05					
)	ADMIN	<u> </u>				
	SEC BR					
	P & DS	1				
3	CSD					
	IPD .					
	PU					
ļ	PSD	ļ				
	PSD-ICB					
نسه دد	110					
7 , 5	IAD	.,				
//						
ح	063					
-	BiAXII-4					
1	ásyá 🧩					
;	MOVITO					
	DIA WE					

MACE

25X1

25X1

25X1

dvance cop:25X1

Approved For Release 200 8B04558A001300030120-2

ANCHOR HOLES HAD BEEN FILLED ON THE RAO CAI BRIDGE AND CABLE ANCHOR HOLES HAD BEEN DUG IN BOTH APPROACHES OF THE NAM QUAT BRIDGE, WHERE CABLES WERE IN PROCESS OF BEING STRUNG.

25X1

MAP REF: GEOGRAPHIC COORDS FROM USATC SERIES 200, SHEET Ø617-14HL UTM COORDS FROM AMS SERIES L701, SHEET 61641 **GP-1**

CONFIDENTIAL

-END OF MESSAGE-